

If a round-shouldered bearing is used,
the snap ring can move, causing the
lip in the housing to break as you can see here.
This can cause a full gearbox failure.

